

1. Incident Name S1 FARMERSVILLE OIL SPILL		2. Operational Period (Date / Time) From: To: Time of Report Start 2/06/2017 1830		INCIDENT STATUS SUMMARY ICS 209-CG	
3. Type of Incident					
<input checked="" type="checkbox"/>	Oil Spill	<input type="checkbox"/>	HAZMAT	<input type="checkbox"/>	AMIO
<input type="checkbox"/>	SAR/Major SART	<input type="checkbox"/>	SI/Terrorism	<input type="checkbox"/>	Natural Disaster
<input type="checkbox"/>	Marine Disaster	<input type="checkbox"/>	Civil Disturbance	<input type="checkbox"/>	Military Outload
<input type="checkbox"/>	Planned Event	<input type="checkbox"/>	Maritime HLS/Prevention	<input type="checkbox"/>	
4. Situation Summary as of Time of Report:					
<ul style="list-style-type: none">Free oil from incident site with vacuum truck is completeAddress seeps as needed with vacuum truckImpacted soil removed from sitePerform air sampling/monitoring					
Recovery Numbers: Liquid Recovered to Date approximately 4359 bbls Liquid Recovered transported 4,329 bbls Soil Removed: Approximately 17,474 tons					
5. Future Outlook/Goals/Needs/Issues:					
<ul style="list-style-type: none">Impacted soil removed and taken to disposal facilityConfirmation sampling complete – Waiting on results					
6. Safety Status/Personnel Casualty Summary					
	Since Last Report	Adjustments To Previous Op Period	Total		
Responder Injury					
NONE					
7. Property Damage Summary					
N/A				\$	
				\$	
				\$	
				\$	
8. Attachments with clarifying information					
<input type="checkbox"/>	Oil/HAZMAT	<input type="checkbox"/>	SAR/LE	<input type="checkbox"/>	
<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>	
<input type="checkbox"/>	Marine Disaster	<input type="checkbox"/>	Civil Disturbance	<input type="checkbox"/>	Military Outload
9. Equipment Resources					



Zone 2 (facing SW toward S15 Line from S1)



Zone 2 (facing SW toward S15 Line from midpoint)



Zone 2 (facing SW from S15 Line)



Zone 1 (facing NE from Lime Tank)